

Installation Instructions for Shielding





1. Remove the screws in the PE bag and fix the hood to the light fixture along the dotted line.

Technical requirements:
1.Material: Galvanized sheet

WSD LED INC Green Lighting Resources			edition	Modifier	Time of modification	Repair the interior	
Material No.	317.0036	Edition	A/0	Page 1/1	Tolerance requirements:(tolerance without special requirements)		Date
Material Name	WSD-AL-150W-HOOD-D	proportion		Angle	NO ±0.2	mapping	
Specification Description		unit			.x ±0.1 .xx ±0.05	check	
Drawing Number		material quality			.xxx±0.015	examine and verify	