




Installation Instructions for Shielding














1. Remove the screws in the PE bag and fix the hood to the light fixture along the dotted line.

Technical requirements:
1. Material: Galvanized sheet

WSD LED INC Green Lighting Resources			edition	Modifier	Time of modification	Repair the interior	
Material No.	317.0037	Edition	A/0	Page 1/1	Tolerance requirements:(tolerance without special requirements)		Date
Material Name	WSD-AL-300W-HOOD-D	proportion		Angle	NO ± 0.2	mapping	
Specification Description		unit			.x ± 0.1	check	
Drawing Number		material quality			.xx ± 0.05 .xxx± 0.015	examine and verify	